

Contact issues when fitting a longer (aftermarket) shock to a T300 series Triumph

